




DRY CLEANER'S BOILER EXPERIENCES RUPTURE, CAUSING SHUTDOWN OF OPERATION



LOSS DETAILS

Nature of Business: Dry Cleaner
Type of Equipment: Vertical Fire Tube Boiler
Age of Equipment: 9 years

Final Loss Settlement:

Property Damage	\$21,152.00
Business Interruption	\$5,455.00
Total	\$26,607.00

During an inspection of this boiler, which provided 100-psi steam to clothing presses, an 8-inch bulge was discovered. It was located inside, on the waterside of the boiler and caused a 1-inch crack on the inner shell weld. This is a common occurrence due to heavy scale and sediment buildup.

It was determined, in the best interest of the insured, to replace this boiler with a new one within seven days, rather than repair it, taking three weeks. In the replacement process, walls within the dry cleaner were removed and reinstalled, allowing access.

To prevent a reoccurrence, daily blowdowns and a water treatment plan were instituted by the insured.

***The Boiler Inspection and Insurance Company of Canada
Brings Engineering and Inspection to Insurance***